

# **MRW** Technologies

Lemcar Industrial Park    Tel. (845) 628-1445  
Buckshollow Road        Fax (845) 628-1344  
PO Box 847                MRWSERVICE@MSN.COM  
Mahopac, NY 10541  
Date: 4/22/2014



## **ABM Ferguson Gearbox Type MH-2**

**OEM # 64 307070010**

### **GEARBOX OVERHAUL**

#### **MINIMUM CONDITION OF THE GEARBOX:**

- Gearbox must still be assembled
- Castings must be in good condition
- 45 degree Cam

#### **OVERHAUL TYPES THAT ARE MOST COMMON:**

1. Input shaft with standard taper lock bushing, bearings seals, and cam followers.
2. New cam, input shaft with standard taper lock bushing, bearings, seals, and cam followers. Includes fitting the cam to the gearbox, (most common type of overhaul).
3. New cam, output shaft, input shaft with standard taper lock bushing bearings, seals, and cam followers. Includes fitting the cam to the gearbox (very time consuming). At this point all the moving parts in the gearbox have been replaced.
4. New output shaft, input shaft with standard taper lock bushing. Includes fitting the output shaft to the gearbox.
5. Gearbox exchange.

#### **Price List:**

1. Input shaft timing belt pulley with taper lock bushing, bearings, seals, and cam followers.    **Cost: Please call**
2. New cam, input shaft with standard taper lock bushing, bearings, seals, and cam followers. Includes fitting the cam to the gearbox which can be very time consuming.    **Cost: Please call**
3. New cam, output shaft, input shaft with standard taper lock bushing, bearings, seals, and cam followers. Includes fitting the cam to the gearbox (very time consuming) at this point all the moving parts in the gearbox have been replaced.    **Cost: Please call**
4. New output shaft, input shaft with standard taper lock bushing. Includes fitting the output shaft to the gearbox.    **Cost: Please call**
5. Gearbox Exchange:    **Cost: Please call**  
Pending audit. Exchange includes input shaft and cam. If output shaft is needed (normally not the case) there is an additional cost.